



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
December 19, 2006

Supervisor

QRZ

Mine Name: Nine Mile Quarry

Operator Name: Danny Bown

Permit number: M/039/010

Inspection Date: 11/15&16, 2006

Time: 3:00 pm and 8:30 am

Inspector(s): Lynn Kunzler, DOGM

Other Participants: Jerome Bown, Matthew Bown, Danny Bown

Mine Status: Site being Reclaimed

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Operator had requested inspection of final reclamation work.

Inspection Summary:

9. Upon arrival at the site, the operator was in the process of seeding this site. Seeding was being done by broadcast methods. Prior to seeding, the area had been roughened, utilizing an excavator. Upon return to the site on the morning of the 16th, it was noted the entire site had been seeded.

Conclusions and Recommendations:

The status of this file should be changed to reclaimed. Division should continue to visit this site when in the area to monitor revegetation establishment.

Inspector's Signature

[Signature]

Date: December 19, 2006

LK:pb

O:\M039-Sanpete\S0390010-Ninemile\inspections\insp-11162006.doc